

Inspector: Rachel Koehler

**Inspection Date:** 12/1/2006

**Building:** Clearview Elementary **Location:** Exterior Building by Door 5

Type of Space: Manhole Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/1/2006

**Photo Description**Manhole



Inspector: Rachel Koehler

**Inspection Date:** 12/1/2006

**Building:** Clearview Elementary **Location:** Exterior Building by Door 7

Type of Space: Manhole Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/1/2006

**Photo Description**Manhole



**Inspector:** Rachel Koehler **Inspection Date:** 12/01/2006

**Building:** Clearview Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

**Other Considerations:** 

Asbestos

City sewer or water

Gas lines Poor lighting Steam pipes

Comments: Tunnel runs along the east side of the building.




Photo Date: 12/1/2006

**Photo Description**Tunnel access in Boiler Room.



Inspector: Rachel Koehler

**Inspection Date:** 12/1/2006

**Building:** Clearview Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards: No Hazards

Number of Entries into Space: 1

**Other Considerations:** 

Asbestos

City sewer or water

Electrical
Gas lines
Poor lighting
Steam pipes

Comments: Tunnel runs along the south side of the building.



Photo Date: 12/1/2006

Photo Description
Tunnel access in Boiler
Room.



Inspector: Rachel Koehler

**Inspection Date:** 12/1/2006

**Building:** Clearview Elementary

**Location:** Boiler Room **Type of Space:** Sump

Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment

Number of Entries into Space: /

Other Considerations:

Biological

City sewer or water Slick/wet surfaces

Comments: Lockout/Tagout procedures for pumps are required

prior to entry.



Photo Date: 12/1/2006

**Photo Description** 

Sump

EN LA

Inspector: Rachel Koehler

**Inspection Date:** 12/1/2006

**Building:** Clearview Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

Other Considerations:

Asbestos

City sewer or water

Electrical
Gas lines
Poor lighting
Steam pipes

Comments: Tunnels runs along the west side of the building.




Photo Date: 12/1/2006

Photo Description
Tunnel access in Boiler
Room.

Page # 10