EA CA

Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High

Location: South Gym Behind Bleachers

Type of Space: Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

Other Considerations:

City sewer or water

Electrical Poor lighting

Comments: Bleachers must be opened to access hatch.



Photo Date: 1/23/2007

Photo Description
Tunnel access behind bleachers.



Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High **Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 4

Other Considerations:

Asbestos

City sewer or water

Electrical Poor lighting Steam pipes

Comments: Tunnel travels throughout building.



Photo Date: 1/23/2007

Photo Description
Tunnel access in Boiler
Room.



Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High **Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

Other Considerations:

City sewer or water

Electrical

Poor lighting

Comments: Tunnel travels around pool.



Photo Date: 1/23/2007

Photo Description
Tunnel access in Boiler
Room.

EL P

Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High

Location: Exterior Building West Parking Lot

Type of Space: Storm sewer (2) Space Classification: Permit

Potential Hazards:

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 1/23/2007

Photo Description

Storm Sewer



Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High

Location: Exterior Building East side

Type of Space: Fuel oil tank Space Classification: Permit

Potential Hazards:

Flammable in excess of its LFL Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

Poor lighting Slick/wet surfaces

Comments: Tank must be emptied prior to entry.




Photo Date: 1/23/2007

Photo DescriptionFuel Oil Tank

EN S

Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High Location: Pool/Music Elevator Type of Space: Elevator shaft Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

Other Considerations:

Electrical
Fall hazards
Falling objects

Comments: Lockout/Tagout procedures for elevator are

required prior to entry.



Photo Date: 1/23/2007

Photo Description

Elevator

EA

Inspector: Rachel Koehler

Inspection Date: 1/23/2007

Building: South Junior High Location: Academics Elevator Type of Space: Elevator shaft Space Classification: Non-Permit

Potential Hazards:

Number of Entries into Space: 1

Other Considerations:

Electrical Fall hazards Falling objects

Comments: Lockout/Tagout procedures for elevator are

required prior to entry.



Photo Date: 1/23/2007

Photo Description

Elevator