

Inspector: Rachel Koehler

**Inspection Date:** 12/20/2006

**Building:** Discovery Elementary

Location: Exterior Building West Courtyard

Type of Space: Storm sewer Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None




Photo Date: 12/20/2006

EN

Inspector: Rachel Koehler

**Inspection Date:** 12/20/2006

Building: Discovery Elementary Location: Boiler Room Penthouse Type of Space: Boiler stack Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

 $Other\ Considerations:$ 

Falling objects
Poor lighting
Temperature extremes

Comments: Lockout/Tagout procedures for boilers are required

prior to entry.



Photo Date: 12/20/2006

**Photo Description**Boiler Stack



**Inspector:** Rachel Koehler **Inspection Date:** 12/20/2006

**Building:** Discovery Elementary

**Location:** Boiler Room **Type of Space:** Boiler #1

Space Classification: Non-Permit

Potential Hazards: No Hazards

Number of Entries into Space: 1

Other Considerations:

Electrical
Gas lines
Temperature extremes

Comments: Lockout/Tagout procedures for boiler are required

prior to entry.



Photo Date: 12/20/2006

**Photo Description** 

Boiler #1



**Inspector:** Rachel Koehler **Inspection Date:** 12/20/2006

**Building:** Discovery Elementary

**Location:** Boiler Room **Type of Space:** Boiler #2

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 1

**Other Considerations:** 

Electrical Gas lines

Temperature extremes

Comments: Lockout/Tagout procedures for boiler are required

prior to entry.



Photo Date: 12/20/2006

**Photo Description** 

Boiler #2



Inspector: Rachel Koehler

Inspection Date: 12/20/2006

Building: Discovery Elementary Location: Exterior Building North side Type of Space: Storm sewer (2) Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/20/2006



**Inspector:** Rachel Koehler **Inspection Date:** 12/20/2006

Building: Discovery Elementary Location: Exterior Building West side Type of Space: Storm sewer (2) Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/20/2006



**Inspector:** Rachel Koehler **Inspection Date:** 12/20/2006

Building: Discovery Elementary
Location: Exterior Building South side
Type of Space: Storm sewer (2)
Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/20/2006



**Inspector:** Rachel Koehler **Inspection Date:** 12/20/2006

**Building:** Discovery Elementary **Location:** Exterior Building East side

Type of Space: Storm sewer Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: /

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces Comments: None



Photo Date: 12/20/2006

EA

**Inspector:** Rachel Koehler

**Inspection Date:** 12/20/2006

**Building:** Discovery Elementary **Location:** Exterior Building North side

Type of Space: Storm sewer Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: /

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 12/20/2006