## **Confined Space Inventory for Saint Cloud Public Schools**

EA.

**Inspector:** Rachel Koehler **Inspection Date:** 11/16/2006

**Building:** Lincoln Elementay **Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

**Potential Hazards:** No Hazards

Number of Entries into Space: 7

Other Considerations:

Asbestos

City sewer or water

Electrical Poor lighting Steam pipes

Comments: Tunnel travels throughout building except east

wing.



Photo Date: 11/16/2006

Photo Description
Tunnel access in Boiler
Room.

## **Confined Space Inventory for Saint Cloud Public Schools**



Inspector: Rachel Koehler

**Inspection Date:** 11/16/2006

**Building:** Lincoln Elementay

Location: Exterior Building West side

Type of Space: Storm sewer Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 11/16/2006

**Photo Description**Storm Sewer

## **Confined Space Inventory for Saint Cloud Public Schools**



**Inspector:** Rachel Koehler **Inspection Date:** 11/16/2006

**Building:** Lincoln Elementay **Location:** East Entrance **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards: No Hazards

Number of Entries into Space: 3

Other Considerations:

Asbestos

City sewer or water

Electrical Poor lighting Steam pipes

Comments: Tunnel travels throughout the east wing.



Photo Date: 11/16/2006

**Photo Description**Tunnel access off east entrance.