

Inspector: Rachel Koehler

Inspection Date: 1/8/2007

Building: McKinley Center **Location:** Mechanical Room G21

Type of Space: Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 2

Other Considerations:

Asbestos

City sewer or water

Electrical Poor lighting Steam pipes

Comments: Tunnel travels throughout south side of building.



Photo Date: 1/8/2007

Photo Description
Tunnel access from
Mechanical Room G21.

Inspector: Rachel Koehler

Inspection Date: 1/8/2007

Building: McKinley Center Location: Boiler Room Type of Space: Sump

Space Classification: Permit

Potential Hazards:

Potential for oxygen deficiency

Engulfment

Number of Entries into Space: 1

Other Considerations:

Biological

City sewer or water

Slick/wet surfaces

Comments: Lockout/Tagout procedures for pumps are required

prior to entry.




Photo Date: 1/8/2007

Photo Description

Sump



Inspector: Rachel Koehler

Inspection Date: 1/8/2007

Building: McKinley Center

Location: Exterior Building North side **Type of Space:** Storm sewer (2)

Space Classification: Permit

Potential Hazards:

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 1/8/2007

Photo Description
Storm Sewer



Inspector: Rachel Koehler

Inspection Date: 1/8/2007

Building: McKinley Center

Location: Elevator

Type of Space: Elevator shaft Space Classification: Non-Permit

Potential Hazards:

Number of Entries into Space: 1

Other Considerations:

Electrical
Fall hazards
Falling objects

Comments: Lockout/Tagout procedures for elevator are

required prior to entry.




Photo Date: 1/8/2007

Photo Description

Elevator