

**Inspector:** Rachel Koehler **Inspection Date:** 12/12/2006

**Building:** Westwood Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

**Potential Hazards:** *No Hazards* 

Number of Entries into Space: 5

Other Considerations:

Asbestos

City sewer or water

Electrical
Gas lines
Poor lighting
Steam pipes

Comments: Tunnel travels throughout the northeast side of the

building.



Photo Date: 12/12/2006

Photo Description
Tunnel access in Boiler
Room.

EA

Inspector: Rachel Koehler

Inspection Date: 12/12/2006

**Building:** Westwood Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

**Potential Hazards:**No Hazards

Number of Entries into Space: 4

Other Considerations:

Asbestos

City sewer or water

Electrical
Gas lines
Poor lighting
Steam pipes

Comments: Tunnel travels throughout the northwest side of the

building.




Photo Date: 12/12/2006

Photo Description
Tunnel access in Boiler
Room.



**Inspector:** Rachel Koehler **Inspection Date:** 12/12/2006

**Building:** Westwood Elementary

**Location:** Boiler Room **Type of Space:** Tunnel

Space Classification: Non-Permit

Potential Hazards:
No Hazards

Number of Entries into Space: 2

Other Considerations:

Asbestos

City sewer or water

Electrical
Gas lines
Poor lighting
Steam pipes

Comments: Tunnel travels throughout the southeast side of the

building.



Photo Date: 12/12/2006

Photo Description
Tunnel access in Boiler
Room.



Inspector: Rachel Koehler

Inspection Date: 12/12/2006

**Building:** Westwood Elementary

Location: Exterior Building Southwest corner

Type of Space: Storm sewer (2) Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 12/12/2006

**Photo Description**Storm Sewer

EN

Inspector: Rachel Koehler

**Inspection Date:** 12/12/2006

**Building:** Westwood Elementary

Location: Exterior Building Southeast corner

Type of Space: Storm sewer (2) Space Classification: Permit

**Potential Hazards:** 

Potential for oxygen deficiency

Engulfment Configuration

Number of Entries into Space: 1

Other Considerations:

City sewer or water Fall hazards Poor lighting Slick/wet surfaces

Comments: None



Photo Date: 12/12/2006

**Photo Description**Storm Sewer