

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | |
|----------|-----------------------|-------------------|---------------------------|-------------------|-------------------|-------------------|-----------|---------|
| AHS01 | Kitchen | Sink | 4.77 | 0.8 | | | 1.48 | |
| AHS02 | Kitchen | North Kettle | 47.8 | 19.2 | | | 2.11 | |
| AHS03 | Serving Line | Sink | 5.66 | 0.94 | | | 1.64 | |
| AHS04 | Receiving | Sink | 0.61 | 1.11 | | | < 0.5 | |
| AHS05 | Receiving | Cooler | 0.85 | <0.5 | | | < 0.5 | |
| AHS06 | Boys Locker Room | Cooler | <0.5 | <0.5 | | | 0.54 | |
| AHS07 | Girls Locker Room | Cooler | 0.68 | <0.5 | | | 0.5 | |
| AHS08 | S. Hall by Locker Rms | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| AHS09 | Gym SE | Fountain | <0.5 | 1.91 | | | No Sample | REMOVED |
| AHS10 | Gym SW | Fountain | 25.3 | 3.27 | | | No Sample | REMOVED |
| AHS11 | Gym NE | Cooler | 0.71 | <0.5 | | | < 0.5 | |
| AHS12 | Gym NW | Fountain | 4.19 | <0.5 | | | 9.44 | |
| AHS13 | Wellness Center | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| AHS14 | Wellness Center | Fountain | 4.51 | n/a | | | No Sample | REMOVED |
| AHS15 | Cafeteria Commons | South Cooler | 0.6 | 0.7 | | | < 0.5 | |
| AHS16 | Cafeteria Commons | North Cooler | 0.59 | 4.55 | | | 0.89 | |
| AHS17 | Band Office | Sink | 5.65 | 4.83 | | | 1.05 | |
| AHS18 | Faculty Lounge | Sink | 0.97 | 0.66 | | | < 0.5 | |
| AHS19 | Main Office E-W Hall | Cooler | 12.7 | 2.31 | | | 11.1 | |
| AHS20 | Main Office | Sink | 3.43 | 2.29 | | | 0.81 | |
| AHS21 | Waiting Room A27 | Sink | 9.77 | n/a | | | No Sample | REMOVED |
| AHS22 | Hall E of Media | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| AHS23 | Hall W of Media | Cooler | <0.5 | <0.5 | | | 0.73 | |
| AHS24 | Social Studies | Sink | 2.52 | 4.17 | | | 43.6 | REMOVED |
| AHS25 | Copy Rm Conf. Rm | Sink | 2.98 | 6.84 | | | < 0.5 | |
| AHS26 | Snack Kitchen | Coffee Maker Hose | <0.5 | <0.5 | | | 0.66 | |
| AHS27 | Snack Kitchen | South Sink | 25.9 | 2.91 | | | 3.13 | |
| AHS28 | Hall by SW Restrooms | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| AHS29 | Hall by SE Restrooms | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| AHS30 | Home Living Center | Sink | 10.3 | 4.34 | | | 10.1 | |
| AHS31 | Room C910 | SE Fountain | 18 | 10.5 | | | 13.3 | |
| AHS32 | Room C910 | West Fountain | 22.4 | 4.38 | | | 5.92 | |
| AHS33 | Room C911 | Fountain | 7.51 | 4.13 | | | 13.7 | |
| AHS34 | Room C912 | Fountain in Shop | 7.64 | 10.4 | | | 14.3 | |
| AHS35 | Room C912 | Fountain in Entry | 12.2 | 16.6 | | | 11.4 | |
| AHS36 | Room C914 | Fountain | 1.61 | 1.21 | | | 2.89 | |
| AHS37 | Room C917 | Fountain | 10.5 | 1.34 | | | < 0.5 | |
| AHS38 | Room C918 | Sink | 9.34 | 1.1 | | | 1.62 | |
| AHS39 | Room C814B | Sink | 70.2 | 5.63 | | | 3.9 | |
| AHS40 | Room C814G | Sink | 21.7 | 10.8 | | | 1.94 | |
| AHS41 | Room C813 | East Sink | 2.33 | 1.7 | | | 3.28 | |
| AHS42 | Room C813 | West Sink | 4.66 | 2.11 | | | 2.64 | |
| AHS43 | Room C813 | North NE Sink | 3.4 | 2.03 | | | 83.5 | |
| AHS44 | Room C813 | North Sink | 51 | 0.96 | | | 15.9 | |
| AHS45 | Room C813 | NW Sink | 5.89 | 4.07 | | | 1.75 | |
| AHS46 | Room C813 | South Sink | 13.4 | n/a | | | 2.91 | |
| AHS47 | Room C812 | North Sink | 89.6 | n/a | | | No Sample | REMOVED |
| AHS48 | Room C812 | NE Sink | 670 | n/a | | | No Sample | REMOVED |
| AHS49 | Room C812 | East Sink | 154 | 20.1 | | | 99.1 | REMOVED |
| AHS50 | Room C812 | SE Sink | 58.5 | n/a | | | No Sample | REMOVED |
| AHS51 | Room C812 | South Sink | 42.1 | 27.5 | 37 | 17.5 | 22.8 | REMOVED |
| AHS52 | Room C812 | Demo Sink | 16.6 | n/a | | | No Sample | REMOVED |
| AHS53 | Kitchen | South Kettle | 4.11 | n/a | | | 3.33 | REMOVED |
| AHS54 | Kitchen | Mixer Hose | 3 | <0.5 | | | No Sample | REMOVED |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | | | | |
|--|--|--|--|--|--|--|--|--|
| | | | | | | | | |
|--|--|--|--|--|--|--|--|--|

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2018-1st | |
|----------|---------------------------|--------------|---------------------------|-------------------|-----------|---------|
| CV01 | Room 118 | Fountain | 3.14 | 3.45 | < 0.5 | |
| CV02 | Room 117 | Fountain | 6.9 | 4.68 | < 0.5 | |
| CV03 | Room 116 | Sink | 4.01 | 3.86 | < 0.5 | |
| CV04 | Room 115 | Fountain | 3.47 | 1.63 | REMOVED | |
| CV05 | Room 114 | Fountain | 3.63 | 1.68 | 1.45 | |
| CV06 | Room 113 | Fountain | 3.96 | 2.54 | 1.37 | |
| CV07 | Room 112 | Fountain | 3.32 | 1.14 | No Sample | REMOVED |
| CV08 | Room 111 | Fountain | 3.02 | 0.84 | 0.86 | |
| CV09 | Room 110 | Fountain | 2.89 | 1.47 | 1.36 | |
| CV10 | Room 109 | Fountain | 2.98 | 0.95 | < 0.5 | |
| CV11 | Kitchen | NE Sink | 0.67 | 6.16 | 1.34 | |
| CV12 | Kitchen | Kettle | 11.5 | 14.1 | 5.32 | |
| CV13 | Hall by Cafeteria | Cooler | <0.5 | <0.5 | No Sample | REMOVED |
| CV14 | Art Workroom by Cafeteria | North Sink | 49.1 | 0.72 | No Sample | REMOVED |
| CV15 | Cafeteria NE Office | South Sink | 17.3 | <0.5 | No Sample | REMOVED |
| CV16 | Lounge | West Sink | 6.41 | 2.62 | < 0.5 | |
| CV17 | Lounge | East Sink | 3.33 | 2.65 | 0.5 | |
| CV18 | Hall by Main Office | Cooler | 0.5 | <0.5 | 0.58 | |
| CV19 | Nurses Office | Sink | 6.89 | 2.37 | < 0.5 | |
| CV20 | Room 128 | Fountain | 7.96 | 4.23 | No Sample | REMOVED |
| CV21 | Room 127 | Fountain | 517 | 8.2 | No Sample | REMOVED |
| CV22 | Room 126 | Fountain | 12.4 | 10.7 | No Sample | REMOVED |
| CV23 | Room 125 | Fountain | 9.2 | 5.04 | No Sample | REMOVED |
| CV24 | Room 200 | Sink | 0.71 | <0.5 | < 0.5 | |
| CV25 | Room 201 | Sink | <0.5 | <0.5 | < 0.5 | |
| CV26 | Room 202 | Sink | 0.85 | 0.64 | < 0.5 | |
| CV27 | Room 203 | Sink | 0.59 | <0.5 | < 0.5 | |
| CV28 | Room 204 | Sink | 1.76 | 1.08 | < 0.5 | |
| CV29 | Hall by Room 112 | Cooler | 3.05 | 1.45 | No Sample | REMOVED |
| CV30 | West Hall by Restrooms | Mid Cooler | <0.5 | <0.5 | No Sample | REMOVED |
| CV31 | West Hall by Restrooms | South Cooler | <0.5 | <0.5 | < 0.5 | |
| CV32 | Room 205 | Sink | <0.5 | 1.71 | < 0.5 | |
| CV33 | Room 206 | Sink | 0.62 | 0.94 | < 0.5 | |
| CV34 | Room 207 | Sink | 0.7 | <0.5 | < 0.5 | |
| CV35 | Room 122 | Fountain | 13.1 | 7.73 | 5.82 | |
| CV36 | Room 121 | Fountain | 6.62 | 5.52 | 2.97 | |
| CV37 | Room 120 | Fountain | 7.96 | 7.11 | < 0.5 | |
| CV38 | Room 119 | Sink | 9.5 | 2.14 | < 0.5 | |
| CV39 | Kitchen | SW Sink | 1.65 | 2 | < 0.5 | |
| CV40 | Kitchen | Center Sink | <0.5 | 1.29 | < 0.5 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | |
|----------|-----------------|--------------|---------------------------|-------------------|-------------------|-------------------|----------|---------|
| DIS01 | Room 101 | Fountain | 4.07 | 1.82 | | | 1.03 | |
| DIS02 | Room 102 | Fountain | <0.5 | 1.52 | | | 0.94 | |
| DIS03 | Room 107 | Fountain | <0.5 | 1.41 | | | 1.23 | |
| DIS04 | Room 108 | Fountain | 0.55 | 2.76 | | | 1.5 | |
| DIS05 | Room 109 | Fountain | <0.5 | 1.2 | | | 1.83 | |
| DIS06 | Room 110 | Fountain | <0.5 | 1.02 | | | 1.36 | |
| DIS07 | Room 111 | Fountain | <0.5 | 1.46 | | | 0.76 | |
| DIS08 | Room 112 | Fountain | 0.74 | 0.97 | | | 1.05 | |
| DIS09 | Room 113 | Fountain | <0.5 | 1.15 | | | 1.32 | |
| DIS10 | Room 114 | Fountain | <0.5 | 1.17 | | | 1.41 | |
| DIS11 | Room 115 | Fountain | <0.5 | 1.33 | | | 0.7 | |
| DIS12 | Room 116 | Fountain | <0.5 | 1.15 | | | 1.34 | |
| DIS13 | Room 117 | Fountain | <0.5 | 0.95 | | | 0.8 | |
| DIS14 | SE Restroom | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| DIS15 | SE Restroom | Fountain | <0.5 | 17.2 | | | < 0.5 | |
| DIS16 | Room 119 | Fountain | <0.5 | 1.15 | | | 1.26 | |
| DIS17 | Room 120 | Fountain | <0.5 | 1.46 | | | 2.6 | |
| DIS18 | Room 121 | Fountain | <0.5 | 1.3 | | | 1.64 | |
| DIS19 | Room 122 | Fountain | <0.5 | 2.14 | | | 3.42 | |
| DIS20 | Room 123 | Fountain | <0.5 | 0.62 | | | 1.21 | |
| DIS21 | Room 124 | Fountain | <0.5 | 3.48 | | | 2.49 | |
| DIS22 | Room 125 | Fountain | Sample Lost | 2.83 | | | 1.7 | |
| DIS23 | Room 128 | Fountain | <0.5 | 1.21 | | | 1.13 | |
| DIS24 | Room 129 | Fountain | <0.5 | 2.06 | | | 2.47 | |
| DIS25 | Room 130 | Fountain | 0.53 | 1.8 | | | 1.05 | |
| DIS26 | Room 131 | Fountain | <0.5 | 1.69 | | | 0.98 | |
| DIS27 | Room 132 | Fountain | 1.07 | 1.48 | | | 1.37 | |
| DIS28 | Room 133 | Fountain | <0.5 | 1.08 | | | 1.54 | |
| DIS29 | Room 134 | Fountain | <0.5 | 1.45 | | | 1.33 | |
| DIS30 | Room 135 | Fountain | <0.5 | 1.65 | | | 1.28 | |
| DIS31 | Room 136 | Fountain | <0.5 | 1.39 | | | 1.22 | |
| DIS32 | SW Restroom | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| DIS33 | SW Restroom | Fountain | | 13.3 | | | < 0.5 | |
| DIS34 | Room 138 | Fountain | <0.5 | 1.05 | | | 1.05 | |
| DIS35 | Room 139 | Fountain | <0.5 | 1.83 | | | 1.13 | |
| DIS36 | Room 140 | Fountain | 0.62 | 1.78 | | | 1.26 | |
| DIS37 | Room 141 | Fountain | <0.5 | 1.72 | | | 0.94 | |
| DIS38 | Room 142 | Fountain | <0.5 | 1.13 | | | 0.73 | |
| DIS39 | Room 143 | Fountain | <0.5 | 1.02 | | | 0.68 | |
| DIS40 | Room 144 | Fountain | <0.5 | 1.57 | | | 1.36 | |
| DIS41 | Room 145 | Fountain | <0.5 | 0.75 | | | 1.37 | |
| DIS42 | Room 146 | Fountain | <0.5 | 0.76 | | | 1 | |
| DIS43 | Room 155 | Sink | <0.5 | 0.53 | | | 1.13 | |
| DIS44 | Room 147 | Fountain | <0.5 | 1.41 | | | 1.15 | |
| DIS45 | Room 151 | Fountain | 2.54 | 1.98 | | | 4.21 | |
| DIS46 | Room 212 | Sink | <0.5 | 1.08 | | | 0.96 | |
| DIS47 | Room 214 | Cooler | 0.57 | 1.47 | | | 1.21 | |
| DIS48 | Kitchen | West Sink | 5.86 | 16.1 | | | 4.19 | REMOVED |
| DIS49 | Kitchen | North Kettle | 5.97 | 73 | 29.6 | 14.2 | 112 | REMOVED |
| DIS50 | Kitchen | Mid Kettle | 33.7 | 15.2 | | | 6.43 | |
| DIS51 | Kitchen | South Kettle | 2.24 | 9.27 | | | 25.4 | REMOVED |
| DIS52 | Kitchen | East Sink | 3.14 | 5.53 | | | 7.56 | |
| DIS53 | Nurses Office | Sink | <0.5 | 11.4 | | | 1.23 | |
| DIS54 | Office Workroom | Sink | <0.5 | 1.62 | | | 1.31 | |
| DIS55 | Restroom 206 | Cooler | <0.5 | 0.53 | | | < 0.5 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | | | | |
|-------|-----------------------|----------|-------------|------|--|--|-----------|---------|
| DIS56 | Restroom 206 | Fountain | <0.5 | 7.3 | | | < 0.5 | |
| DIS57 | Restroom 202 | Cooler | <0.5 | 1.54 | | | < 0.5 | |
| DIS58 | Restroom 202 | Fountain | <0.5 | 2.11 | | | < 0.5 | |
| DIS59 | Gym-South | Cooler | 1.11 | 1.09 | | | 1 | |
| DIS60 | Gym-Mid | Cooler | 0.59 | 0.81 | | | 0.9 | |
| DIS61 | Gym-North | Cooler | 1.17 | 0.93 | | | 1.28 | |
| DIS62 | Room 162 South Island | SE Sink | 3.86 | 12.5 | | | 7.51 | |
| DIS63 | Room 162 North Island | SE Sink | 7.45 | 0.94 | | | 5.41 | |
| DIS65 | Room 163 South Island | SE Sink | 1.39 | 7.58 | | | No Sample | REMOVED |
| DIS65 | Room 163 North Island | SE Sink | 60.6 | 16.9 | | | No Sample | REMOVED |
| NEW | DIS-62 ROOM 152 | Sink | | | | | 2.16 | |
| NEW | DIS-60 ROOM 162 | Sink | | | | | 1.02 | |
| NEW | DIS-61 ROOM 153 | Sink | | | | | < 0.5 | |

St. Cloud ISD #742
Lead in Water Testing

| Sample# | Sample Description | Fixture | 2018 Result | 2ND Round |
|---------|----------------------------|----------|-------------|-----------|
| K-02 | K-2 KITCHEN SOUTH WALL | SINK | 20.7 | 3.35 |
| K-03 | K-3 KITCHEN SOUTH WALL | SINK | 46.5 | 2.39 |
| K-04 | K-4 KITCHEN EAST WALL | SINK | 3.91 | |
| K-05 | K-5 KITCHEN EAST WALL | SINK | 11.9 | |
| K-06 | K-6 KITCHEN ISLAND | SINK | 13.5 | |
| K-07 | K-7 KITCHEN GRAY | POT | 8.99 | |
| K-08 | K-8 KITCHEN STEAM | KETTLE | 7.6 | |
| K-09 | K-9 KITCHEN BRAISER | FAUCET | 21 | |
| K-1 | K-1 RECEIVING LOUNGE | FOUNTAIN | 4.56 | |
| K-10 | K-13 OUTSIDE RM 600 | FOUNTAIN | < 0.5 | |
| K-11 | K-14 OUTSIDE RM 600 | COOLER | < 0.5 | |
| K-12 | K-15 ROOM 313 | SINK | 5.32 | |
| K-13 | K-16 ROOM 313 | SINK | 11.4 | |
| K-14 | K-17 ROOM 313 | SINK | 7.94 | |
| K-15 | K-18 ROOM 313 | SINK | 6.78 | |
| K-16 | K-19 ROOM 313 | SINK | 4.1 | |
| K-17 | K-20 ROOM 313 | SINK | 5.63 | |
| K-18 | K-21 ROOM 317 | SINK | 4.57 | |
| K-19 | K-22 ROOM 317 | SINK | 7.1 | |
| K-20 | K-23 ROOM 317 | SINK | 6.29 | |
| K-21 | K-24 ROOM 317 | SINK | 29.8 | 3.35 |
| K-22 | K-25 ROOM 317 | SINK | 22.9 | 2.15 |
| K-23 | K-26 ROOM 317 | SINK | 17.8 | |
| K-24 | K-27 OUTSIDE RM 327 BOYS | FOUNTAIN | < 0.5 | |
| K-25 | K-28 OUTSIDE RM 327 BOYS | FOUNTAIN | < 0.5 | |
| K-26 | K-29 OUTSIDE RM 327 GIRLS | FOUNTAIN | < 0.5 | |
| K-27 | K-30 OUTSIDE RM 327 GIRLS | FOUNTAIN | < 0.5 | |
| K-28 | K-31 TEAM RM 409 | FOUNTAIN | 5.75 | |
| K-29 | K-32 ACROSS HALL RM 409 | FOUNTAIN | 1.17 | |
| K-30 | K-34 ROOM 412 1 SINK | SINK | 5.12 | |
| K-31 | K-35 ROOM 412 2 SINK | SINK | 6.26 | |
| K-32 | K-36 ROOM 412 3 SINK | SINK | 3.64 | |
| K-33 | K-37 ROOM 412 4 SINK | SINK | 4.09 | |
| K-34 | K-38 ROOM 412 5 SINK | SINK | 4.04 | |
| K-35 | K-39 ROOM 412 6 SINK | SINK | 5.17 | |
| K-36 | K-40 OUTSIDE RM 423 BOYS | FOUNTAIN | < 0.5 | |
| K-37 | K-41 OUTSIDE RM 423 BOYS | FOUNTAIN | < 0.5 | |
| K-38 | K-42A OUTSIDE RM 423 GIRLS | FOUNTAIN | < 0.5 | |
| K-39 | K-42B OUTSIDE RM 423 GIRLS | FOUNTAIN | 0.62 | |
| K-40 | K-43 GYM NE WALL | FOUNTAIN | 0.93 | |
| K-41 | K-45 GYM SE WALL | FOUNTAIN | 0.58 | |
| K-42 | K-46 GYM SE WALL | COOLER | 0.51 | |
| K-43 | K-47 OUTSIDE RM 524 TALL | FOUNTAIN | 1.2 | |
| K-44 | K-48 OUTSIDE RM 524 | FOUNTAIN | 1.43 | |
| K-45 | K-49 OUTSIDE RM 524 TALL | FOUNTAIN | 1.12 | |
| K-46 | K-50 OUTSIDE RM 524 | FOUNTAIN | 1.18 | |
| K-47 | K-51 ROOM 528 | SINK | 5.15 | |
| K-48 | K-52 ROOM 529 | SINK | 5.22 | |
| K-49 | K-52 ROOM 514 | SINK | 5.54 | |
| K-50 | K-54 ROOM 514 | SINK | 5.99 | |
| K-51 | K-55 ROOM 514 | SINK | 5.74 | |
| K-52 | K-56 ROOM 511 1 | SINK | 4.63 | |
| K-53 | K-57 ROOM 511 2 | SINK | 5.64 | |
| K-54 | K-58 ROOM 511 3 | SINK | 5.76 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | |
|------|-----------------------------|----------|-------|--|--|
| K-55 | K-59 NURSES OFFICE | SINK | 6.8 | | |
| K-56 | K-60 STAFF LOUNGE | SINK | 4.56 | | |
| K-57 | K-62 ACROSS HALL RM 126 | FOUNTAIN | 0.67 | | |
| K-58 | K-63 ACROSS HALL RM 126 | FOUNTAIN | 0.61 | | |
| K-59 | K-64 ROOM 205 | SINK | 6.93 | | |
| K-60 | K-65 ROOM 205 | SINK | 5.85 | | |
| K-61 | K-66 ROOM 203 | SINK | 6.41 | | |
| K-62 | K-67 ROOM 203 | SINK | 7.15 | | |
| K-63 | K-68 ACROSS HALL ROOM 200 | FOUNTAIN | 0.88 | | |
| K-64 | K-69 ACROSS HALL ROOM 200 | FOUNTAIN | 0.91 | | |
| K-65 | K-70 ROOM 201 | SINK | 5.68 | | |
| K-66 | K-71 ROOM 201 | SINK | 5.45 | | |
| K-67 | K-72 ROOM 199 | SINK | 1.26 | | |
| K-68 | K-73 ROOM 199 | SINK | 1.08 | | |
| K-69 | K-74 OUTSIDE GROUP RM | FOUNTAIN | 1.23 | | |
| K-70 | K-75 OUTSIDE GROUP RM | FOUNTAIN | 1.39 | | |
| K-71 | K-76 ROOM 204 | SINK | 6.8 | | |
| K-72 | K-77 ROOM 198 | SINK | 1.22 | | |
| K-73 | K-78 ROOM 200 | SINK | 5.35 | | |
| K-74 | K-79 ROOM 202 | SINK | 8.2 | | |
| K-75 | K-80 ROOM 212 | SINK | 4.24 | | |
| K-76 | K-81 ROOM 213 | SINK | 4.72 | | |
| K-77 | K-82 ROOM 214 | SINK | 4.18 | | |
| K-78 | K-83 ROOM 215 | SINK | 4.59 | | |
| K-79 | K-84 ROOM 216 | SINK | 4.38 | | |
| K-80 | K-85 ROOM 217 | SINK | 4.23 | | |
| K-81 | K-86 ROOM 218 | SINK | 3.83 | | |
| K-82 | K-87 ROOM 219 | SINK | 1.41 | | |
| K-83 | K-88 ROOM 220 | SINK | 1.72 | | |
| K-84 | K-89 ROOM 221 | SINK | 1.17 | | |
| K-85 | K-90 ROOM 222 | SINK | 1.46 | | |
| K-86 | K-91 OUTSIDE ROOM BOYS | FOUNTAIN | < 0.5 | | |
| K-87 | K-92 OUTSIDE ROOM BOYS | FOUNTAIN | < 0.5 | | |
| K-88 | K-93 OUTSIDE ROOM 219 GIRLS | FOUNTAIN | < 0.5 | | |
| K-89 | K-94 OUTSIDE ROOM 219 GIRLS | FOUNTAIN | < 0.5 | | |
| K-90 | Room 317 Teacher Sink | SINK | 1.2 | | |
| K-91 | Room 313 West - Right | SINK | 1.27 | | |
| K-92 | Room 313 West - Left | SINK | 1.24 | | |
| K-93 | Staff Lounge Filtered Water | FAUCET | < 0.5 | | |
| K-94 | GYM - NE Wall | COOLER | 0.67 | | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2018-1st | |
|----------|------------------------------|------------------|---------------------------|-------------------|----------|---------|
| LIN01 | Room 1 | Sink | 4.47 | 1.21 | 2.86 | |
| LIN02 | Room 2 | Sink | 3.42 | 1.77 | 0.92 | |
| LIN03 | Room 3 | Sink | 3.84 | 1.07 | 1.97 | |
| LIN04 | Room 4 | Fountain | 0.76 | 2.24 | 2.09 | |
| LIN05 | Room 5 | Sink | 1.98 | 3.23 | 1.22 | |
| LIN06 | Room 6 | Fountain | 6.04 | 1.86 | 1.02 | |
| LIN07 | Room 7 | Sink | 8.33 | 1.23 | < 0.5 | |
| LIN08 | Room 8 | Sink | 8.39 | 1.29 | 1.12 | |
| LIN09 | Room 9 | Sink | 8.83 | 1.09 | 1.53 | |
| LIN10 | Nurses Office | Sink | 0.97 | 10.3 | 3.79 | |
| LIN11 | Hall by Principals Office | Cooler | <0.5 | <0.5 | < 0.5 | |
| LIN12 | Lounge | Sink | <0.5 | <0.5 | < 0.5 | |
| LIN13 | Kitchen | Sink | 2.85 | 0.9 | < 0.5 | |
| LIN14 | Kitchen | Kettle | 7.06 | 4.71 | 0.92 | |
| LIN15 | Gym | Fountain | 1.79 | 0.71 | < 0.5 | |
| LIN16 | Room 2 | Sink by Restroom | 10.2 | 7.51 | < 0.5 | |
| LIN17 | Room 14 | Sink | 4.25 | 15.6 | 35 | REMOVED |
| LIN18 | Room 15 A/B | Sink | 20 | 4.72 | 2.77 | |
| LIN19 | Room 17 | Sink | 2.31 | 0.64 | < 0.5 | |
| LIN20 | Room 19 | Sink | 2.27 | 0.87 | < 0.5 | |
| LIN21 | Room 20 | Sink | 2.64 | 0.69 | 0.6 | |
| LIN22 | Room 21 | Sink | 2.63 | 0.65 | < 0.5 | |
| LIN23 | Room 22 | Sink | 2.34 | 1.2 | < 0.5 | |
| LIN24 | Room 23 | Sink | 3.81 | 2.04 | < 0.5 | |
| LIN25 | Room 24 | Sink | 3.73 | 2.17 | 0.53 | |
| LIN26 | Room 25 | Sink | 2.77 | 2.51 | < 0.5 | |
| LIN27 | Hall By Room 21 | Cooler | <0.5 | <0.5 | < 0.5 | |
| LIN28 | Hall By Room 21 | Cooler | 6.11 | 9.22 | < 0.5 | |
| LIN29 | Room 16 Outside Restroom | Sink | 6.11 | 9.22 | < 0.5 | |
| LIN30 | Room 3 | Fountain | 1.21 | 2.38 | 0.52 | |
| LIN31 | Room 4 | Sink | 5.86 | 1.68 | 0.59 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2018-1st | 2018-2nd |
|----------|--------------------------|-------------|---------------------------|-------------------|-----------|----------------|
| MAD01 | Room B130 | Fountain | 3.98 | 3.18 | 1.49 | |
| MAD02 | Room B132 | Fountain | 1.92 | 1.58 | 0.76 | |
| MAD03 | Room B133 | Fountain | 1.97 | 0.92 | 3.05 | |
| MAD04 | Room B131 | Sink | 3.36 | 2.75 | 3.27 | |
| MAD05 | Room A120 | Fountain | <0.5 | 0.94 | < 0.5 | |
| MAD06 | Kitchen | South Sink | 7.86 | 8.28 | 1.17 | |
| MAD07 | Kitchen | North Sink | 1.6 | <0.5 | < 0.5 | |
| MAD08 | Kitchen | Kettle | 6.38 | <0.5 | < 0.5 | |
| MAD09 | Room C135 | Fountain | 5.61 | 3.92 | 2.61 | |
| MAD10 | Room C139 | Fountain | 11.5 | 12.3 | 8.35 | |
| MAD11 | Room C141 | Fountain | 12.5 | 14.3 | 3.44 | |
| MAD12 | Room C143 | Fountain | 8.62 | 4.46 | 2.76 | |
| MAD13 | Room C145 | Fountain | 13.5 | 7.86 | 0.64 | |
| MAD14 | Room C144 | Sink | 9.32 | 8.7 | 6.92 | |
| MAD15 | Room C142 | Fountain | 6.73 | 5.78 | 1.92 | |
| MAD16 | Room C140 | Fountain | 1.86 | 2.08 | 2.2 | |
| MAD17 | Room C138 | Fountain | 2.58 | 1.54 | 0.56 | |
| MAD18 | Room C136 | Sink | 22.7 | Removed | No Sample | REMOVED |
| MAD19 | C Wing Hall by Room C146 | Cooler | 0.59 | <0.5 | < 0.5 | |
| MAD20 | C Wing Hall by Room C140 | Cooler | <0.5 | 0.65 | < 0.5 | |
| MAD21 | Room A104 | Sink | 5.55 | 19.4 | 5.98 | |
| MAD22 | Hall Outside A104 | Cooler | <0.5 | <0.5 | < 0.5 | |
| MAD23 | Nurses Office | Sink | 1 | 1.32 | < 0.5 | |
| MAD24 | Room A114 | Sink | 5.59 | 1.17 | 1.39 | |
| MAD25 | Room A113 | Sink | 4.51 | <0.5 | 1.99 | |
| MAD26 | Room A112 | Sink | 1.11 | 0.63 | 1.56 | |
| MAD27 | Room A111 | Sink | 2.15 | 1.66 | 4.73 | |
| MAD28 | Room A110 | Sink | 4.51 | 1.35 | 2.88 | |
| MAD29 | Room A109 | Sink | 3.48 | 1.8 | 1.74 | |
| MAD30 | Room A108 | Sink | 2.39 | 1.12 | 4.35 | |
| MAD31 | Room A107 | Sink | 1.24 | <0.5 | 1.19 | |
| MAD32 | Room A106 | Sink | <0.5 | <0.5 | 1.66 | |
| MAD33 | Room A105 | Fountain | 0.93 | 1.9 | 1.14 | |
| MAD34 | Room D402 | Sink | 4.49 | 1.06 | 1.44 | |
| MAD35 | Room D403 | Sink | 1.45 | 0.72 | 0.62 | |
| MAD36 | Room D406 | Sink | 6.68 | 2.31 | 1.46 | |
| MAD37 | D Wing Hall | West Cooler | <0.5 | <0.5 | <0.5 | |
| MAD38 | D Wing Hall | Mid Cooler | <0.5 | <0.5 | <0.5 | |
| MAD39 | D Wing Hall | East Cooler | <0.5 | <0.5 | <0.5 | |
| MAD40 | Room A101 | Fountain | 2.34 | 1.91 | No Sample | REMOVED |
| MAD41 | Room A100 | Fountain | 2.04 | 1.44 | No Sample | REMOVED |
| MAD42 | Room 118 | Fountain | <0.5 | <0.5 | No Sample | REMOVED |
| MAD43 | Hall by Main Entry | Cooler | <0.5 | <0.5 | < 0.5 | |
| MAD44 | Hall By Boiler Room | Cooler | <0.5 | <0.5 | No Sample | REMOVED |
| MAD45 | Near Engineers Office | Sink | 1.5 | <0.5 | < 0.5 | |
| MAD46 | Hall by A109 | Fountain | 0.62 | <0.5 | 0.91 | |
| MAD47 | ROOM B130 | Sink | NEW LOCATION | | 0.93 | |
| MAD48 | ROOM 131 | Fountain | | | 37.8 | REMOVED |
| MAD49 | ROOM 132 | Sink | NEW LOCATION | | 1.45 | |
| MAD50 | ROOM B133 | Sink | NEW LOCATION | | 0.8 | |
| MAD51 | ROOM 135 | Sink | NEW LOCATION | | 1.1 | |
| MAD52 | ROOM 152 | Sink | NEW LOCATION | | < 0.5 | |
| MAD53 | ROOM 153 | Sink | NEW LOCATION | | < 0.5 | |
| MAD54 | ROOM 155 | Sink | NEW LOCATION | | < 0.5 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | |
|-------|---------------------------|----------|--------------|-------|-------|
| MAD55 | ROOM 156 | Sink | NEW LOCATION | < 0.5 | |
| MAD56 | HALL OUTSIDE 152 | Fountain | NEW LOCATION | < 0.5 | |
| MAD57 | HALL OUTSIDE 146 | Fountain | NEW LOCATION | < 0.5 | |
| MAD58 | HALL OUTSIDE 145 | Fountain | NEW LOCATION | 6.01 | |
| MAD59 | HALL OUTSIDE 140 | Fountain | NEW LOCATION | < 0.5 | |
| MAD60 | HALL BY 121 CUP COOLER | Cooler | NEW LOCATION | < 0.5 | |
| MAD61 | HALL BY 121 FOUNTAIN | Fountain | NEW LOCATION | < 0.5 | |
| MAD62 | ROOM 101 | Sink | NEW LOCATION | 2.11 | |
| MAD63 | ROOM 138 | Sink | NEW LOCATION | 3.22 | |
| MAD64 | ROOM 140 | Sink | NEW LOCATION | 41.9 | < 0.5 |
| MAD65 | ROOM 142 | Sink | NEW LOCATION | 683 | < 0.5 |
| MAD66 | ROOM 144 | Fountain | NEW LOCATION | 1.55 | |
| MAD67 | ROOM 145 | Sink | NEW LOCATION | 17.3 | |
| MAD68 | ROOM 143 | Sink | NEW LOCATION | 10.3 | |
| MAD69 | ROOM 141 | Sink | NEW LOCATION | 7.54 | |
| MAD70 | ROOM 139 | Sink | NEW LOCATION | 10.6 | |
| MAD71 | ROOM 146 | Sink | NEW LOCATION | < 0.5 | |
| MAD72 | ROOM 147 | Sink | NEW LOCATION | < 0.5 | |
| MAD73 | ROOM 148 | Sink | NEW LOCATION | < 0.5 | |
| MAD74 | ROOM 149 | Sink | NEW LOCATION | < 0.5 | |
| MAD75 | ROOM 150 | Sink | NEW LOCATION | < 0.5 | |
| MAD76 | ROOM 151 | Sink | NEW LOCATION | < 0.5 | |
| MAD77 | FOUNTAIN BY 406 #1 CUP CO | Cooler | NEW LOCATION | < 0.5 | |
| MAD78 | FOUNTAIN BY 406 #1 FOUNT | Fountain | NEW LOCATION | < 0.5 | |
| MAD79 | FOUNTAIN BY 406 #2 FOUNT | Fountain | NEW LOCATION | < 0.5 | |
| MAD80 | FOUNTAIN BY 406 #3 FOUNT | Fountain | NEW LOCATION | < 0.5 | |
| MAD81 | HALL BY 104 | Fountain | NEW LOCATION | < 0.5 | |
| MAD82 | KITCHEN KETTLE A | Kettle | NEW LOCATION | 18.8 | |
| MAD83 | KITCHEN KETTLE B | Kettle | NEW LOCATION | < 0.5 | |
| MAD84 | ROOM 115B | Sink | NEW LOCATION | 0.59 | |
| MAD85 | ROOM 115B | Fountain | NEW LOCATION | 1.06 | |
| MAD86 | ROOM 118 UPPER SINK | Sink | NEW LOCATION | < 0.5 | |
| MAD87 | ROOM 118 LOWER SINK | Sink | NEW LOCATION | < 0.5 | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | | |
|----------|-------------------------------|-------------|---------------------------|-------------------|-------------------|-------------------|-----------|---------|--|
| MCK01 | Room 123 | Fountain | 27.1 | 27.8 | 8.5 | | No Sample | REMOVED | |
| MCK02 | Room 124 | Fountain | 4.78 | 8.32 | | | 2.73 | | |
| MCK03 | Room 125 | Fountain | 5.29 | 1.02 | | | 0.59 | | |
| MCK04 | Room 127 | Fountain | 7.74 | 9.4 | | | 1.9 | | |
| MCK05 | Room 128 | Fountain | 6.12 | 15.9 | | | 3.93 | | |
| MCK06 | Room 129 | Fountain | 4.98 | 10.4 | 13.2 | | 4.71 | | |
| MCK07 | Room 130 | Fountain | 4.35 | 22.8 | | | 1.48 | | |
| MCK08 | Room 131 | Fountain | 5.09 | 15.4 | | | 1.98 | | |
| MCK09 | Room 132 | Fountain | 3.82 | 5.49 | | | 2.31 | | |
| MCK10 | Room 105 | Fountain | 17.5 | 12.6 | | | No Sample | REMOVED | |
| MCK11 | Room 114 | Fountain | 58.1 | 60.5 | 6.16 | | 12.7 | | |
| MCK12 | Hall by Restrooms | East Cooler | 1.1 | 2.28 | | | 1.14 | | |
| MCK13 | Hall by Restrooms | West Cooler | 1.53 | 2.04 | | | 0.56 | | |
| MCK14 | Room 115 | Fountain | 30.6 | 2.83 | | | 4.17 | | |
| MCK15 | Room 116 | Fountain | 110 | 14.9 | | | 4.4 | REMOVED | |
| MCK16 | Room 117 | Fountain | 3.88 | 10.6 | | | 7.36 | | |
| MCK17 | Room 118 | Fountain | 8.52 | 10.2 | | | 2.2 | | |
| MCK18 | Office 140 | Sink | 6.24 | <0.5 | | | 11.7 | | |
| MCK19 | Lower Level Hall by Restrooms | Cooler | 1.55 | 8.48 | | | < 0.5 | | |
| MCK20 | East G13 | North Sink | 12.2 | 18.2 | | | No Sample | REMOVED | |
| MCK21 | East G13 | South Sink | 11.4 | 24 | 4.8 | | No Sample | REMOVED | |
| MCK22 | Kitchen | East Sink | 8.44 | 10.9 | | | 2.91 | | |
| MCK23 | Kitchen | West Sink | 4.36 | 22.1 | 56.7 | 9.72 | 1.35 | | |
| MCK24 | HALL BY OFFICE | Fountain | NEW LOCATION | | | | | < 0.5 | |
| MCK25 | HALL BY OFFICE | Cooler | NEW LOCATION | | | | | < 0.5 | |
| MCK26 | Lower Level Hall by Restrooms | Fountain | NEW LOCATION | | | | | < 0.5 | |
| MCK27 | Hall by Restrooms | Cooler | NEW LOCATION | | | | | 1.17 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEF | 2013-1st round | 2018-1st | |
|----------|---------------------------------|------------------------|------------------------|----------------|-----------|---------|
| NJH01 | 2 E Maintenance Office Restroom | Sink | 0.77 | 0.68 | < 0.5 | |
| NJH02 | 2W-Hall by Girls Restroom | Cooler | <0.5 | <0.5 | < 0.5 | |
| NJH03 | 2W-Hall by Girls Restroom | Fountain | 0.96 | <0.5 | No Sample | RENAMED |
| NJH04 | 2W-Hall by Boys Restroom | North Fountain | <0.5 | <0.5 | No Sample | RENAMED |
| NJH05 | 2W-Hall by Boys Restroom | South Fountain | <0.5 | <0.5 | No Sample | RENAMED |
| NJH06 | 2W-Teachers Workrm. 239 | Sink | 22.1 | 0.67 | 876 | REMOVED |
| NJH07 | 2W-Science Storage 238 | Sink | 12.4 | 11.3 | No Sample | REMOVED |
| NJH08 | Girls Locker Room | Fountain | 2.6 | 0.87 | No Sample | RENAMED |
| NJH09 | Boys Locker Room | Fountain | 3.07 | 0.96 | No Sample | RENAMED |
| NJH10 | South Hall by Gym | Cooler | <0.5 | <0.5 | No Sample | RENAMED |
| NJH11 | South Hall by Gym | Fountain | 1.37 | 0.6 | No Sample | RENAMED |
| NJH12 | North Hall by Gym | Cooler | <0.5 | <0.5 | No Sample | RENAMED |
| NJH13 | North Hall by Gym | Fountain | 1.7 | <0.5 | No Sample | RENAMED |
| NJH14 | Gym | North Cooler | <0.5 | <0.5 | No Sample | RENAMED |
| NJH15 | Gym | South Cooler | 0.61 | <0.5 | No Sample | RENAMED |
| NJH16 | East Art Room 103 | 1 of 4 Sinks East Sink | 4.04 | 0.68 | < 0.5 | |
| NJH17 | West Art Room 102 | 1 of 2 Sinks West Sink | 5 | 2.53 | < 0.5 | |
| NJH18 | Cafeteria | Fountain | 1.4 | <0.5 | No Sample | REMOVED |
| NJH19 | Kitchen | West Sink | 4.13 | 4 | 0.83 | |
| NJH20 | Kitchen Center Hand | Center Sink | 4.44 | 7.49 | < 0.5 | |
| NJH21 | Kitchen | East Sink | 1.06 | 1.46 | < 0.5 | |
| NJH22 | Kitchen | Kettle | 3.93 | 1.97 | 0.61 | |
| NJH23 | Foods Room 138 - N. Wall | Sink | 2.76 | 4.29 | No Sample | REMOVED |
| NJH24 | Foods Room 138 - E. Wall | North Sink | 0.89 | 1.96 | No Sample | REMOVED |
| NJH25 | Foods Room 138 - E. Wall | Center Sink | 2.12 | 3.91 | No Sample | REMOVED |
| NJH26 | Foods Room 138 -E. Wall | South Sink | 0.58 | 1.47 | No Sample | REMOVED |
| NJH27 | Foods Room 138 -W. Wall | North Sink | 2.63 | 2.57 | No Sample | REMOVED |
| NJH28 | Foods Room 138 -W. Wall | Center Sink | 4.89 | 2.15 | No Sample | REMOVED |
| NJH29 | Foods Room 138-W. Hall | South Sink | 1.49 | 1.68 | 10 | |
| NJH30 | Room 134 | Sink | 4.89 | 0.6 | 10.5 | |
| NJH31 | Room 133 | Fountain | 5.57 | 4.94 | 16.5 | |
| NJH32 | Teachers Lounge | Sink | 0.64 | <0.5 | 1.39 | |
| NJH33 | Hall by West Boys Restoom | North Fountain | 0.53 | no sample | No Sample | RENAMED |
| NJH34 | Hall by West Boys Restoom | South Fountain | <0.5 | <0.5 | No Sample | RENAMED |
| NJH35 | Hall by West Girls Restoom | Cooler | 1.24 | <0.5 | No Sample | RENAMED |
| NJH36 | Hall by West Girls Restoom | Fountain | n/a | | No Sample | RENAMED |
| NJH37 | Special Ed Classroom | Sink | 3.86 | <0.5 | No Sample | RENAMED |
| NJH38 | Nurses Office | Sink | 4.65 | 1.02 | 3.33 | |
| NJH39 | Nurses Office Restroom | Sink | 1.82 | 0.99 | 5.47 | |
| NJH40 | Main Office Hall | Fountain | 1.91 | 1.74 | 1.11 | |
| NJH41 | Hall Outside Main Office | Cooler | n/a | 1.52 | 33.4 | 2.71 |
| NJH42 | Main Office A110 | Sink | 4.83 | 0.56 | No Sample | REMOVED |
| NHH43 | KITCHEN SOUTH SINK 2 OF 2 | Sink | NEW LOCATION | | 13.3 | |
| NJH44 | ROOM A139 | Sink | NEW LOCATION | | 10.1 | |
| NJH45 | FAUCET RM A216 SW | Sink | NEW LOCATION | | 4.76 | |
| NJH46 | FOUNTAIN RM A216 SW | Fountain | NEW LOCATION | | 3.63 | |
| NJH47 | ROOM A217 FAUCET SE | Sink | NEW LOCATION | | 3.53 | |
| NJH48 | ROOM A217 FAUCET SW | Sink | NEW LOCATION | | 3.2 | |
| NJH49 | FAUCET RM A214 SOUTH | Sink | NEW LOCATION | | 2.55 | |
| NJH50 | FAUCET WEST SINK A213 | Sink | NEW LOCATION | | 2.52 | |
| NJH51 | KITCHEN SOUTH SINK 1 OF 2 | Sink | NEW LOCATION | | 2.23 | |
| NJH52 | RM A272 NORTH FAUCET | Sink | NEW LOCATION | | 2 | |
| NJH53 | RM A272 WEST SINK | Sink | NEW LOCATION | | 1.33 | |
| NJH54 | FAUCET RM A216 SE | Sink | NEW LOCATION | | 1.23 | |
| NJH55 | FAUCET EAST SINK A213 | Sink | NEW LOCATION | | 1.08 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | |
|-----------------------------|-----------------------------|----------|--------------|-------|--|
| NJH56 | BOILER ROOM SINK | Sink | NEW LOCATION | 0.96 | |
| NJH57 | RM A190 WEST SINK | Sink | NEW LOCATION | 0.81 | |
| NJH58 | FAUCET RM A215 SOUTH | Sink | NEW LOCATION | 0.64 | |
| NJH59 | FOUNTAIN BY GIRLS RR A157 | Fountain | NEW LOCATION | 0.54 | |
| NJH60 | FOUNTAIN BY GIRLS RR A234 | Fountain | NEW LOCATION | < 0.5 | |
| NJH61 | FAUCET RM A214 NORTH | Sink | NEW LOCATION | < 0.5 | |
| NJH62 | FAUCET RM A215 NORTH | Sink | NEW LOCATION | < 0.5 | |
| NJH63 | FOUNTAIN BY A233 BOYS RR | Fountain | NEW LOCATION | < 0.5 | |
| NJH64 | E FOUNTAIN BY G263 | Fountain | NEW LOCATION | < 0.5 | |
| NJH65 | BOTTLE FILLER BY G263 | Cooler | NEW LOCATION | < 0.5 | |
| NJH66 | W FOUNTAIN BY G263 | Fountain | NEW LOCATION | < 0.5 | |
| NJH67 | RM A272 SOUTH SINK | Sink | NEW LOCATION | < 0.5 | |
| NJH68 | RM A272 EAST SINK | Sink | NEW LOCATION | < 0.5 | |
| NJH69 | RM G251 MUSIC SINK | Sink | NEW LOCATION | < 0.5 | |
| NJH70 | E DRINKING FOUNTAIN BY A171 | Fountain | NEW LOCATION | < 0.5 | |
| NJH71 | W DRINKING FOUNTAIN BY A171 | Fountain | NEW LOCATION | < 0.5 | |
| NJH72 | BOTTLE FILLER BY A171 | Cooler | NEW LOCATION | < 0.5 | |
| NJH73 | RM A190 NW SINK | Sink | NEW LOCATION | < 0.5 | |
| NJH74 | RM A190 NORTH CENTER SINK | Sink | NEW LOCATION | < 0.5 | |
| NJH75 | NE SINK RM A190 | Sink | NEW LOCATION | < 0.5 | |
| NJH76 | RM A190 SOUTH SINK | Sink | NEW LOCATION | < 0.5 | |
| | | | | | |
| 2W = Second Floor West Wing | | | | | |
| 2E = Second Floor East Wing | | | | | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2018-1st | |
|----------|-----------------------|-------------|---------------------------|-------------------|----------|--|
| OH01 | Kitchen | North Sink | 1.4 | 2.48 | 1.42 | |
| OH02 | Kitchen | South Sink | 1.02 | 7.11 | 0.6 | |
| OH03 | Kitchen | East Kettle | 9.21 | 9.05 | 3.66 | |
| OH04 | Kitchen | West Kettle | 11.4 | 6.09 | 8.91 | |
| OH05 | Receiving | Sink | 1.05 | 0.52 | 1.7 | |
| OH06 | Room 143 | Fountain | <0.5 | 0.54 | 1.45 | |
| OH07 | Room 142 | Fountain | 0.9 | <0.5 | 2.65 | |
| OH08 | Room 141 | Fountain | <0.5 | <0.5 | 0.5 | |
| OH09 | Cafeteria | Cooler | <0.5 | <0.5 | < 0.5 | |
| OH10 | Room 140 | Fountain | 0.75 | <0.5 | < 0.5 | |
| OH11 | Room 139 | Fountain | <0.5 | 1.11 | 1.57 | |
| OH12 | Room 138 | Fountain | 0.93 | 1.03 | 1.73 | |
| OH13 | Room 137 | Fountain | 0.51 | 0.61 | 1.55 | |
| OH14 | Room 136 | Fountain | 0.76 | 0.59 | 0.84 | |
| OH15 | Room 135 | Fountain | 0.52 | 0.63 | 1.64 | |
| OH16 | Room 134 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH17 | Room 133 | Fountain | 0.61 | 0.67 | 0.79 | |
| OH18 | Restrooms by Room 133 | Cooler | <0.5 | <0.5 | < 0.5 | |
| OH19 | Restrooms by Room 133 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH20 | Room 131 | Fountain | 0.72 | 1.13 | 1.21 | |
| OH21 | Room 130 | Fountain | <0.5 | <0.5 | 0.54 | |
| OH22 | Room 129 | Fountain | 0.89 | 0.64 | 1.11 | |
| OH23 | Room 128 | Fountain | <0.5 | 0.93 | 0.78 | |
| OH24 | Room 127 | Fountain | <0.5 | 0.58 | 0.82 | |
| OH25 | Room 126 | Fountain | <0.5 | <0.5 | 0.86 | |
| OH26 | Room 150C | Sink | <0.5 | <0.5 | < 0.5 | |
| OH27 | Room 125 | Fountain | <0.5 | <0.5 | 0.59 | |
| OH28 | Room 123 | Fountain | 0.69 | <0.5 | 1.21 | |
| OH29 | Room 122 | Fountain | <0.5 | 0.58 | 0.66 | |
| OH30 | Room 121 | Fountain | 0.77 | <0.5 | 2.42 | |
| OH31 | Room 120 | Fountain | <0.5 | 0.79 | 2.3 | |
| OH32 | Room 119 | Fountain | <0.5 | <0.5 | 3.56 | |
| OH33 | Room 117 | Fountain | <0.5 | <0.5 | 0.63 | |
| OH34 | Restrooms by Room 117 | Cooler | <0.5 | <0.5 | < 0.5 | |
| OH36 | Room 116 | Fountain | <0.5 | <0.5 | 1.95 | |
| OH37 | Room 115 | Fountain | <0.5 | <0.5 | 2.52 | |
| OH38 | Room 114 | Fountain | 0.52 | 0.81 | 1.44 | |
| OH39 | Room 113 | Fountain | 0.59 | <0.5 | < 0.5 | |
| OH40 | Room 112 | Fountain | 0.52 | <0.5 | 0.56 | |
| OH41 | Room 111 | Fountain | <0.5 | <0.5 | 1.29 | |
| OH42 | Room 110 | Fountain | 0.78 | 0.74 | 1.56 | |
| OH43 | North Wing Hall | West Cooler | <0.5 | <0.5 | < 0.5 | |
| OH44 | Room 304 | Fountain | 1.25 | <0.5 | 0.98 | |
| OH45 | Room 305 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH46 | Room 306 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH47 | Room 307 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH48 | 308 Fountain | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH49 | Room 309 | Fountain | 1.21 | 0.81 | < 0.5 | |
| OH50 | Room 105 | Fountain | 0.88 | <0.5 | < 0.5 | |
| OH51 | Room 104 | Fountain | 0.74 | <0.5 | < 0.5 | |
| OH52 | Room 101 | Fountain | 1.47 | 0.93 | 1.93 | |
| OH53 | Gym 201 | Cooler | <0.5 | 1.12 | 0.54 | |
| OH54 | Gym 201L | Cooler | <0.5 | <0.5 | 1.4 | |
| OH55 | Room 152 | West Sink | 0.62 | <0.5 | 0.9 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | | |
|------|---------------------------------|----------------|------|------|-----------|---------|
| OH56 | Room 152 | East Fountain | <0.5 | 0.73 | 1.05 | |
| OH57 | Room 151 Center Island of Sinks | NE Sink 1 of 8 | <0.5 | <0.5 | < 0.5 | |
| OH58 | Staff Lounge 148 | Sink | <0.5 | <0.5 | < 0.5 | |
| OH59 | Room 147 | Fountain | <0.5 | 0.78 | 1.41 | |
| OH60 | Restrooms by Room 151 | Cooler | <0.5 | <0.5 | < 0.5 | |
| OH61 | Restrooms by Room 151 | Fountain | N/A | <0.5 | < 0.5 | |
| OH62 | Restrooms by Room 149 | Cooler | 0.66 | <0.5 | < 0.5 | |
| OH63 | Restrooms by Room 149 | Fountain | <0.5 | <0.5 | < 0.5 | |
| OH64 | Room 204 | Sink | 6.04 | 6.63 | 0.6 | |
| OH65 | Nurses Office | Sink | <0.5 | <0.5 | < 0.5 | |
| OH66 | Office Workroom | Sink | <0.5 | <0.5 | < 0.5 | |
| OH67 | Nurses Office Restroom | Sink | 5.3 | | 7.69 | |
| OH68 | North Wing Hall | East Cooler | <0.5 | n/a | no sample | Removed |
| | Restrooms by Room 117 | Fountain | N/A | n/a | | Removed |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2018-1st |
|----------|----------|---------|----------|
| RW-1 | KITCHEN | Sink | < 0.5 |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2018-1st |
|----------|-----------------------------|----------|---------------------------|----------------|----------|
| R1 | Room 27 | Sink | 12 | 2.5 | |
| R2 | Room 26 | Sink | 8.78 | 7.38 | |
| R3 | Room 25 | Sink | 5.86 | 5.42 | |
| R4 | North Drinking Fountain | Fountain | 1.17 | 1.04 | |
| R5 | Lounge/Kitchen | Sink | 4.48 | 0.61 | |
| R6 | Health Office | Sink | 2.58 | 8.81 | |
| R7 | Room 3 | Sink | <0.5 | <0.5 | |
| R8 | Room 6 | Sink | 5.33 | 0.67 | |
| R9 | Room 7 | Sink | 1.14 | 1.37 | |
| R10 | East Drinking Fountain | Fountain | 0.99 | 2.04 | |
| R11 | Room 9 | Sink | 0.82 | 0.92 | |
| R12 | Room 19 | Sink | 15.8-3.67 | 1.33 | |
| R13 | Room 18 | Sink | 3.25 | 1.55 | |
| R14 | Room 17 | Sink | <0.5 | <0.5 | |
| R15 | West Drinking Fountain | Fountain | <0.5 | <0.5 | |
| R16 | Room 16 | Sink | <0.5 | <0.5 | |
| R17 | Room 14 | Sink | 76.8-46.9 | 6.19 | |
| R18 | Boys/Girls Restroom | Sink | 1.12 | 1.7 | |
| | | | | | |
| 1 | KITCHEN 209 | Sink | New Building | | < 0.5 |
| 2 | STAFF LOUNGE | Sink | New Building | | < 0.5 |
| 3 | WALL OUTSIDE BATHROOMS TALL | Fountain | New Building | | < 0.5 |
| 4 | WALL OUTSIDE BATHROOMS LOW | Fountain | New Building | | < 0.5 |
| 5 | WALL OUTSIDE BATHROOMS | Cooler | New Building | | < 0.5 |
| 6 | ELEMENTARY TALL | Fountain | New Building | | < 0.5 |
| 7 | ELEMENTARY LOW | Fountain | New Building | | < 0.5 |
| 8 | ELEMENTARY COOLER | Cooler | New Building | | < 0.5 |
| 9 | HIGH SCHOOL TALL | Fountain | New Building | | < 0.5 |
| 10 | HIGH SCHOOL LOW | Fountain | New Building | | < 0.5 |
| 11 | HIGH SCHOOL COOLER | Cooler | New Building | | < 0.5 |
| 12 | IN STEP TALL | Fountain | New Building | | < 0.5 |
| 13 | IN STEP LOW | Fountain | New Building | | < 0.5 |
| 14 | IN STEP | Cooler | New Building | | < 0.5 |
| 15 | ROOM 201 | Sink | New Building | | < 0.5 |
| 16 | ROOM 203 | Sink | New Building | | < 0.5 |
| 17 | LAUNDRY ROOM | Sink | New Building | | < 0.5 |
| 18 | CONFERENCE ROOM | Sink | New Building | | < 0.5 |
| 19 | IN STEP KITCHEN | Sink | New Building | | < 0.5 |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | |
|----------|--|-------------------|---------------------------|-------------------|-------------------|-------------------|-----------|---------|
| SJH01 | 2-Band 252 | Sink | 1.72 | 3.99 | | | 6.16 | |
| SJH02 | 2-Hall Outside Band | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| SJH03 | 2-Workroom 224 | Sink | 9.74 | 22.5 | | | 4.17 | |
| SJH04 | 2-Library Office | Sink | 7.43 | n/a | | | No Sample | REMOVED |
| SJH05 | 2-Hall by Restroom Lower Fountain | Fountain | 0.6 | <0.5 | | | < 0.5 | |
| SJH06 | 2-Hall by Restroom Upper Fountain | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| SJH07 | 2-Art Room 203 | North Sink | 6.56 | 11.7 | | | < 0.5 | |
| SJH08 | 2-Art Room 203 | South Sink | 69 | 32.4 | 119 | 1.96 | < 0.5 | |
| SJH09 | Girls Locker Room | Fountain | 1.2 | 3.22 | | | 1.86 | |
| SJH10 | Boys Locker Room | Fountain | <0.5 | n/a | | | No Sample | REMOVED |
| SJH11 | Hall by Boys Locker Room | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| SJH12 | Gym | North Fountain | <0.5 | <0.5 | | | < 0.5 | |
| SJH13 | Gym | South Fountain | <0.5 | <0.5 | | | < 0.5 | |
| SJH14 | Wood Shop Room 159 | Sink | 2.27 | 1.9 | | | 1.75 | |
| SJH15 | Metals Room 155 | East Sink 1 of 4 | 0.83 | 1.63 | | | < 0.5 | |
| SJH16 | Graphic Arts Room 153 | South Sink 1 of 2 | 3.19 | 14.4 | | | 9.3 | |
| SJH17 | Cafeteria | Fountain | 1.22 | 2.05 | | | < 0.5 | |
| SJH18 | Kitchen | East Sink | <0.5 | <0.5 | | | < 0.5 | |
| SJH19 | Kitchen | Center Sink | 0.64 | 3.5 | | | 1.91 | |
| SJH20 | Kitchen | West Sink | 2.1 | 3.58 | | | 2.8 | |
| SJH21 | Kitchen | Brazier | 10.9 | 8.26 | | | < 0.5 | |
| SJH22 | Kitchen Restroom | Sink | 3.37 | 14 | | | 4.87 | |
| SJH23 | Hall by West Boys Restroom Upper | Fountain | <0.5 | 0.64 | | | < 0.5 | |
| SJH24 | Hall by West Boys Restroom Lower | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| SJH25 | Teachers Lounge | Sink | <0.5 | 1.05 | | | 0.76 | |
| SJH26 | Room 117 | North Sink | 6.4 | 1.2 | | | 0.78 | |
| SJH27 | Room 119 | North Sink | 1.07 | 0.6 | | | < 0.5 | |
| SJH28 | Room 119 West Wall | North Sink | 10.4 | n/a | | | No Sample | REMOVED |
| SJH29 | Room 119 West Wall | Center Sink | 3.7 | n/a | | | No Sample | REMOVED |
| SJH30 | Room 119 West Wall | South Sink | 7 | n/a | | | No Sample | REMOVED |
| SJH31 | Room 119 | South Sink | 0.58 | n/a | | | No Sample | REMOVED |
| SJH32 | Room 119 East Wall | North Sink | 1.49 | n/a | | | No Sample | REMOVED |
| SJH33 | Room 119 East Wall | South Sink | 35.2 | n/a | | | No Sample | REMOVED |
| SJH34 | Room 121 | Fountain | 15.5 | 14.7 | | | 5.52 | |
| SJH35 | Room 123 | Fountain | 7.38 | 5.45 | | | No Sample | REMOVED |
| SJH36 | Room 125 | Sink | 12.9 | 1.22 | | | No Sample | REMOVED |
| SJH37 | Room 127 | Fountain | 10.3 | 8.95 | | | No Sample | REMOVED |
| SJH38 | Room 129 | Sink | 3.37 | 415 | 68.9 | 8.9 | No Sample | REMOVED |
| SJH39 | Room 101 | Sink | 4.22 | 5.71 | | | No Sample | REMOVED |
| SJH40 | Hall Outside Main Office | Cooler | 0.69 | 0.61 | | | < 0.5 | |
| SJH41 | Nurses Office | Sink | 1.93 | 3.63 | | | 2.57 | |
| SJH42 | Main Office Hall | Cooler | <0.5 | <0.5 | | | No Sample | REMOVED |
| SJH43 | Room 117 | South Sink | 11.8 | n/a | | | No Sample | REMOVED |
| SJH44 | Nurses Cot Room | Sink | 4.64 | 11 | | | 4.63 | |
| SJH45 | MAIN OFFICE STAFF KITCHEN SINK | Sink | NEW LOCATION | | | | < 0.5 | |
| SJH46 | MAIN OFFICE RESTROOM | Fountain | NEW LOCATION | | | | 1.61 | |
| SJH47 | NEW NURSES RESTROOM | Fountain | NEW LOCATION | | | | < 0.5 | |
| SJH48 | 6TH GRADE HALLWAY BOYS UPPER FOUNTAIN | Fountain | NEW LOCATION | | | | < 0.5 | |
| SJH49 | 6TH GRADE HALLWAY BOYS LOWER FOUNTAIN | Fountain | NEW LOCATION | | | | < 0.5 | |
| SJH50 | 6TH GRADE HALLWAY GIRLS UPPER FOUNTAIN | Fountain | NEW LOCATION | | | | < 0.5 | |
| SJH51 | 6TH GRADE HALLWAY GIRLS LOWER FOUNTAIN | Fountain | NEW LOCATION | | | | < 0.5 | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | |
|----------|------------------------|---------------|---------------------------|-------------------|-------------------|-------------------|-----------|---------|
| TAL01 | Kitchen | South Kettle | 28 | 26.2 | 22.3 | 6.92 | 62.7 | REMOVED |
| TAL02 | Kitchen | North Kettle | 46.2 | 31.1 | 14.3 | | 10.9 | REMOVED |
| TAL03 | Kitchen | South Sink | <0.5 | <0.5 | | | 0.82 | |
| TAL04 | Kitchen | West Sink | 16 | 17.1 | | | 7.84 | |
| TAL05 | Kitchen Office | Sink | 1.48 | 0.51 | | | < 0.5 | |
| TAL06 | Room 143 | Fountain | 1.01 | 0.82 | | | < 0.5 | |
| TAL07 | Room 142 | Fountain | 0.99 | 3.88 | | | 0.67 | |
| TAL08 | Room 141 | Fountain | 0.89 | 2 | | | < 0.5 | |
| TAL09 | Room 140 | Sink | <0.5 | 0.99 | | | < 0.5 | |
| TAL10 | Room 139 | Fountain | 1.4 | 0.88 | | | < 0.5 | |
| TAL11 | Room 138 | Fountain | 0.81 | 0.8 | | | < 0.5 | |
| TAL12 | Room 137 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL13 | Room 136 | Sink | <0.5 | <0.5 | | | < 0.5 | |
| TAL14 | Room 135 | Fountain | 0.78 | 0.72 | | | 1.43 | |
| TAL15 | Room 134 | Fountain | 0.76 | 1.3 | | | 0.65 | |
| TAL16 | Room 133 | Fountain | 0.54 | 1.12 | | | < 0.5 | |
| TAL17 | Restrooms by Room 133 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| TAL18 | Restrooms by Room 133 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL19 | Room 131 | Fountain | 0.81 | 0.92 | | | < 0.5 | |
| TAL20 | Room 130 | Fountain | 1.12 | 1.04 | | | < 0.5 | |
| TAL21 | Room 129 | Fountain | 1.23 | 3.94 | | | < 0.5 | |
| TAL22 | Room 128 | Fountain | 1.02 | 1.21 | | | < 0.5 | |
| TAL23 | Room 127 | Fountain | 0.68 | 0.93 | | | 18.4 | |
| TAL24 | Room 126 | Fountain | 0.76 | 0.92 | | | < 0.5 | |
| TAL25 | Room 150C | Sink | 1.39 | 12.6 | | | 1.16 | |
| TAL26 | Room 125 | Fountain | 0.96 | 0.84 | | | 3.72 | |
| TAL27 | Room 123 | Fountain | 0.62 | 0.81 | | | < 0.5 | |
| TAL28 | Room 122 | Fountain | 0.8 | 0.68 | | | < 0.5 | |
| TAL29 | Room 121 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL30 | Room 120 | Fountain | 0.72 | 0.78 | | | < 0.5 | |
| TAL31 | Room 119 | Fountain | <0.5 | 0.51 | | | < 0.5 | |
| TAL32 | Room 117 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL33 | Restrooms by Room 117 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| TAL34 | Restrooms by Room 117 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL35 | Room 116 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL36 | Room 115 | Fountain | 0.97 | <0.5 | | | < 0.5 | |
| TAL37 | Room 114 | Fountain | 2.49 | 1.73 | | | < 0.5 | |
| TAL38 | Room 113 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL39 | Room 112 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL40 | Room 111 | Fountain | 0.71 | 2.26 | | | < 0.5 | |
| TAL41 | Room 110 | Fountain | 0.82 | 0.51 | | | < 0.5 | |
| TAL42 | New Addition Hall | North Cooler | <0.5 | <0.5 | | | <0.5 | |
| TAL43 | New Addition Hall | South Cooler | <0.5 | <0.5 | | | < 0.5 | |
| TAL44 | Room 105 | Sink/Fountain | <0.5 | 0.76 | | | < 0.5 | |
| TAL45 | Room 104 | Sink/Fountain | 0.83 | 1.07 | | | < 0.5 | |
| TAL46 | Room 101 | Sink/Fountain | 1.1 | 1.01 | | | No Sample | REMOVED |
| TAL47 | Room 152 | Sink/Fountain | 0.9 | 0.97 | | | < 0.5 | |
| TAL48 | Room 151 South Island | SE Sink | <0.5 | <0.5 | | | < 0.5 | |
| TAL49 | Room 151 North Island | SE Sink | <0.5 | <0.5 | | | < 0.5 | |
| TAL50 | Gym 201R | Cooler | 0.84 | 1.4 | | | 1.01 | |
| TAL51 | Gym 201 | Cooler | 0.72 | 0.76 | | | 0.71 | |
| TAL52 | Gym 201L | Cooler | <0.5 | 0.6 | | | 0.61 | |
| TAL53 | Nurses Office | Sink | <0.5 | <0.5 | | | 13.2 | |
| TAL54 | Nurses Office Restroom | Sink | 7.87 | 9.77 | | | < 0.5 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | | | | |
|-------|-----------------------|----------|-------------|------|--|--|-------|--|
| TAL55 | Room 204 | Sink | 4.43 | 4.67 | | | 2.26 | |
| TAL56 | Restrooms by Room 151 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| TAL57 | Restrooms by Room 151 | Fountain | N/A | 1.04 | | | 0.73 | |
| TAL58 | Restrooms by Room 149 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| TAL59 | Restrooms by Room 149 | Fountain | <0.5 | <0.5 | | | < 0.5 | |
| TAL60 | Staff Lounge 148 | Sink | <0.5 | <0.5 | | | < 0.5 | |
| TAL61 | Room 147 | Sink | <0.5 | <0.5 | | | < 0.5 | |
| TAL62 | Office Workroom | Sink | <0.5 | 1.04 | | | < 0.5 | |
| TAL63 | ROOM 144A | Sink | New Install | | | | < 0.5 | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2018-1st | |
|----------|----------------------------------|-----------------------|---------------------------|-------------------|-------------------|-----------|---------|
| THS01 | Basement 101 | Sink | 6.07 | 7.45 | | 13.9 | |
| ThS02 | Basement Cust. Office | Sink | 0.96 | 0.65 | | 0.67 | |
| THS03 | Basement Cust. Office | Cooler | 1.18 | <0.5 | | < 0.5 | |
| THS05 | 1-WW-Prin. Office Restroom | Sink | 6.72 | 0.7 | | 0.7 | |
| THS06 | 1-WW-Hall by Restroom | Cooler | 0.71 | <0.5 | | 1.48 | |
| THS07 | 1-WW-Hall by Room 161 | Fountain | 22.5 | n/a | | No Sample | REMOVE |
| THS08 | 1-WW-E/W Hall | Cooler | 0.89 | <0.5 | | 3.08 | |
| THS09 | 1-WW-Hall by Room 182 | Fountain | 3.04 | 2.84 | | < 0.5 | |
| THS10 | 1-EW-Girls Locker Room | Fountain | 1.46 | 1.47 | | 2.5 | |
| THS11 | 1-EW-Boys Locker Room | Fountain | 1.07 | 0.95 | | 1.96 | |
| THS12 | 1-EW-Gym 021 | Fountain | 1.82 | <0.5 | | No Sample | REMOVED |
| THS13 | 1-EW-Hall by Restrooms | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS14 | 1-EW-Pool Area | Fountain | 4.62 | 0.72 | | 1.4 | |
| THS15 | 1-EW Concessions | Sink | 1.42 | 1.38 | | 1.58 | |
| THS16 | 1-EW-Gym 016 | North Fountain | <0.5 | <0.5 | | No Sample | REMOVE |
| THS17 | 1-EW-Gym 016 | South Fountain | <0.5 | <0.5 | | No Sample | REMOVED |
| THS18 | 1-EW-Hall East of Gym | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS19 | 1-EW Wrestling 015 | North Fountain | <0.5 | <0.5 | | < 0.5 | |
| THS20 | 1-EW Wrestling 015 | South Fountain | <0.5 | <0.5 | | < 0.5 | |
| THS21 | 1-EW-Auto Shop | Cooler | 1.39 | <0.5 | | < 0.5 | |
| THS22 | 1-EW 008 Synthetics | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS23 | 1-EW Print Shop | West Sink | 11.1 | n/a | | n/a | |
| THS24 | 1-EW Print Shop | East Sink | 2.46 | 3.03 | | 4.38 | |
| THS25 | 1-EW-Hall Outside Print | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS26 | 1-EW 011 Ceramics E. tap by door | Sink 1 of 5 | 0.55 | 2.27 | | 1.14 | |
| THS27 | 1-EW Art 012 | S. Sink W. Tap 1 of 6 | 4.97 | 2.14 | | 2.17 | |
| THS28 | 2-WW-Hall by Girls Restroom | Fountain | <0.5 | <0.5 | | < 0.5 | |
| THS29 | 2-WW-Hall by Boys Restroom | Cooler | 3.8 | 5.24 | | 4.33 | |
| THS30 | 2-EW-Shack East of Media | Sink | 1.1 | <0.5 | | 2.99 | |
| THS31 | 2-EW Workroom 108K | Sink | 6.66 | 7.05 | | 9.78 | |
| THS32 | 2-EW Faculty 114 | Sink | 1.27 | 0.91 | | 2.38 | |
| THS33 | 2-EW-Nurses Office 120 | Sink | 6.8 | 3.21 | | 3.27 | |
| THS34 | 2-EW-Nurses Restroom | Sink | 1.91 | 2.37 | | 5.71 | |
| THS35 | 2-EW-Hall by Nurses Office | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS36 | 2-EW Kitchen | Mixer | 45.6 | 0.75 | | No Sample | REMOVED |
| THS37 | 1-WW Hall By Metals | Fountain | <0.5 | n/a | | No Sample | REMOVE |
| THS38 | 2-EW Kitchen | Kettle | 2.72 | 0.52 | | 0.79 | |
| THS39 | 2-EW Kitchen | Sink (Island) | 13 | <0.5 | | 0.75 | |
| THS4 | 1-WW-Prin. Office | Cooler | 2.79 | <0.5 | | < 0.5 | |
| THS40 | 2-EW Kitchen | Sink | 1.38 | 0.88 | | 0.83 | |
| THS41 | 2-EW Cafeteria | East Cooler | <0.5 | 2.47 | | 2.98 | |
| THS42 | 2-EW Cafeteria | West Cooler | 0.63 | 0.81 | | 0.69 | |
| THS43 | 3-WW-Hall by Boys Restroom | Fountain | 2.65 | 1.28 | | 3.26 | |
| THS44 | 3-WW-Hall by Girls Restroom | Cooler | 0.77 | <0.5 | | < 0.5 | |
| THS45 | 3-EW-Hall by Restroom | Cooler | <0.5 | <0.5 | | 0.56 | |
| THS46 | 3-EW-Hall by Drama 222 | Cooler | <0.5 | <0.5 | | < 0.5 | |
| THS47 | 3-EW Room 218A | Sink | 4.14 | 1.1 | | 0.69 | |
| THS48 | 4-EW-Hall by Restrooms | Cooler | <0.5 | <0.5 | | < 0.5 | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| | | | | | | | |
|-------------------------------|------------------------------|-----------------------------|------|------------|------|-------|--|
| THS49 | 4-EW Home Ec 320 East Island | North Sink | 0.64 | <0.5 | | < 0.5 | |
| THS50 | 4-EW Home Ec 320 East Island | South Sink | 1.66 | <0.5 | | 0.63 | |
| THS51 | 4-EW Home Ec 320 | Laundry Sink | 5,68 | 15.3 | | 10.3 | |
| THS52 | 4-EW Home Ec 320 South Wall | Sink | 1.75 | <0.5 | | < 0.5 | |
| THS53 | 4-EW Home Ec 320 West Island | North Sink | 0.66 | <0.5 | | 2.13 | |
| THS54 | 4-EW Home Ec 320 West Island | South Sink | 2.12 | <0.5 | | < 0.5 | |
| THS55 | 4-EW Home Ec 320 Restroom | Sink | 9.34 | 146 | 1.23 | 13 | |
| | | | | | | | |
| 1-WW = First Fl | | 3-WW=Third Floor West Wing | | | | | |
| 1-EW = First Floor East Wing | | 3-EW=Third Floor East Wing | | | | | |
| 2-WW = Second Floor West Wing | | 4-EW=Fourth Floor East Wing | | | | | |
| 2-EW = Second Floor East Wing | | | | | | | |

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018-1st | |
|----------|---------------------------|----------------|---------------------------|-------------------|-------------------|-------------------|-----------|----------------|
| WW01 | Room 117 | Fountain | 1.04 | 1.5 | | | 1.04 | |
| WW02 | Room 118 | Fountain | 0.84 | 1.44 | | | 1.08 | |
| WW03 | Room 119 | Fountain | 0.7 | 5.54 | | | < 0.5 | |
| WW04 | Room 120 | Fountain | 0.57 | 38.9 | 0.54 | | 1.31 | |
| WW05 | Room 121 | Fountain | 0.59 | 30.8 | 0.84 | | 1.45 | |
| WW06 | Room 122 | Fountain | 0.96 | 10.8 | | | 1.59 | |
| WW07 | Room 123 | Fountain | 1.3 | 2.82 | | | No Sample | REMOVED |
| WW08 | Hall by Room 124 | Cooler | 0.69 | <0.5 | | | 0.53 | |
| WW09 | Room 124 | Fountain | 0.64 | 5.97 | | | 0.77 | |
| WW10 | Room 125 | Fountain | 1.04 | 3.87 | | | < 0.5 | |
| WW11 | Room 126 | Fountain | 5.15 | 3.2 | | | 1.85 | |
| WW12 | Room 175 | Sink | 0.81 | 31.4 | 1.4 | | < 0.5 | |
| WW13 | Hall by Room 43 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| WW14 | Room 10 | Sink | 5.96 | 13.4 | | | 1 | |
| WW15 | Room 23 | Sink | 11.2 | 9.9 | | | 0.75 | |
| WW16 | Room 15 | Sink-Right Tap | 19.9 | 15.5 | | | 1.1 | |
| WW17 | Room 14 | Sink-Right Tap | 3.03 | 10.8 | | | 1.03 | |
| WW18 | Room 127 | Fountain | 0.69 | 0.79 | | | 0.61 | |
| WW19 | Room 128 | Fountain | <0.5 | <0.5 | | | 0.71 | |
| WW20 | Room 129 | Fountain | <0.5 | 0.85 | | | 0.68 | |
| WW21 | Room 130 | Fountain | <0.5 | 0.78 | | | 0.53 | |
| WW22 | Room 178 | Sink | 28.9 | 20.6 | 58 | | No Sample | REMOVED |
| WW23 | Room 179 | West Sink | 51.7 | 165 | 43.3 | 58.4 | No Sample | REMOVED |
| WW24 | Hall by Room 162 | Cooler | <0.5 | <0.5 | | | < 0.5 | |
| WW25 | Kitchen | Kettle | 22.2 | 36 | 22.8 | 7.86 | No Sample | REMOVED |
| WW26 | Kitchen | Hot Water Tap | 2.14 | 0.65 | | | < 0.5 | |
| WW27 | Kitchen | Steam Oven | 1.77 | 8.73 | | | 9.71 | |
| WW28 | Kitchen | Sink | 2.37 | 2.66 | | | < 0.5 | |
| WW29 | Room 204 | Sink | 4.9 | 0.97 | | | 0.54 | |
| WW30 | Room 206 | Sink | 8.74 | <0.5 | | | < 0.5 | |
| WW31 | Room 208 | Sink | 1.4 | <0.5 | | | < 0.5 | |
| WW32 | Room 210 | Sink | 1.28 | 0.72 | | | < 0.5 | |
| WW33 | Room 211 | Sink | 3.87 | 3.11 | | | < 0.5 | |
| WW34 | Room 209 | Sink | 1.45 | 0.57 | | | < 0.5 | |
| WW35 | New Addition by Restrooms | West Cooler | <0.5 | <0.5 | | | < 0.5 | |
| WW36 | New Addition by Restrooms | East Cooler | <0.5 | <0.5 | | | < 0.5 | |
| WW37 | Room 131 | Fountain | 1.46 | 6.86 | | | 1.46 | |
| WW38 | Room 132 | Fountain | 0.93 | 1.73 | | | 1.54 | |
| WW39 | Room 133 | Fountain | 1.65 | 3.29 | | | 4.1 | |
| WW40 | Room 134 | Fountain | 1.17 | 1.34 | | | 0.81 | |
| WW41 | Room 135 | Fountain | 1.32 | 2.08 | | | 1.93 | |
| WW42 | Room 137 | Fountain | 1.7 | n/a | | | No Sample | REMOVED |
| WW43 | Room 138 | Fountain | 1.25 | 7.46 | | | 0.93 | |
| WW44 | Room 139 | Fountain | 0.89 | 1.6 | | | 1.67 | |
| WW45 | Room 140 | Fountain | 0.7 | 1.54 | | | 1.82 | |
| WW46 | Room 141 | Fountain | 0.77 | 21.1 | 1.14 | | 3.65 | |
| WW47 | Nurses Office | Sink | 2.97 | 2.03 | | | 6.32 | |
| WW48 | Hall by Main Office | Cooler | <0.5 | <0.5 | | | 2.45 | |
| WW49 | Main Office | Sink | 5.18 | n/a | | | No Sample | REMOVED |
| WW50 | Teachers Lounge 157 | Sink | 1.08 | 0.53 | | | 1.32 | |
| WW51 | Computer Room | Sink | | no sample | | | 35.2 | REMOVED |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013-1st round | 2013-2nd round | 2013-3rd round | 2018 Result |
|----------|--------------------------------|-----------|---------------------------|-------------------|-------------------|-------------------|----------------|
| DSB1 | Warehouse | Cooler | | | 1.36 | 1.84 | 2.03 |
| DSB2 | Lounge | Cooler | | | 1.34 | 1.12 | 0.67 |
| DSB3 | Custodial Storage by Lounge | Slop Sink | | | 1.48 | 7.18 | 0.71 |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2008 Result (ug/L) IEA | 2013 Result (ug/L) | 2018 Result | | |
|----------|-----------------|----------|---------------------------|-----------------------|----------------|--|--|
| DAO1 | | Sink | N/A | N/A | <0.5 | | |
| DAO2 | | Sink | N/A | N/A | <0.5 | | |
| DAO3 | | Sink | | | <0.5 | | |
| DAO4 | | Sink | | | <0.5 | | |
| DAO5 | 1st Floor Upper | Fountain | | | <0.5 | | |
| DAO6 | 1st Floor Lower | Fountain | | | <0.5 | | |
| DAO7 | 2nd Floor Upper | Fountain | | | <0.5 | | |
| DAO8 | 2nd Floor Lower | Fountain | | | <0.5 | | |

ug/L = Micrograms per liter

St. Cloud ISD #742
Lead in Water Testing

| Sample # | Location | Fixture | 2023 Result (ug/L) IEA | | | |
|----------|----------|---------|---------------------------|--|--|--|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

ug/L = Micrograms per liter